

On




88888888



0.00 g

Off





Switching on

- Remove any load from weighing pan and press «On» key briefly.
The balance performs a display test (all segments in the display light up briefly).
When zero is displayed, the balance is ready for operation.

Switching off

- Press and hold the «Off» key down until "OFF" appears in the display. Release the key.



- Place weighing sample on the weighing pan.
- Wait until the stability detector "o" disappears.
- Read the result.