


Taring



0.00 g

12.101 g



0.00 g



95.97 g



- 12.101 g

→ Place empty container on the balance.

→ The weight is displayed.

→ Tare: press the « →0/T← » key briefly.

→ Add weighing sample to container. The net weight is now

If the container is removed from the balance, the tare weight is subtracted.
The tare weight remains stored until the « →0/T← » key is pressed.